



BYD LVL 15.4 update

BYD Battery-Box



LVL Two Handles for Easier Lifting Up

Before



After



LVL Rear Cable Entry for **Neat and Tidy Cabling**

Before



After



LVL Improvement – Intuitive Design, Less Onsite Work


Before



- Three cables need to be connected




After



- Only two busbars required
- No need to connect BIC cables
- Mistake proofing


LVL Improvement – Compatible with old version



New Version

Old Version





BATTERY
BOX