



▲ DANGER / PELIGRO / DANGER



HAZARDOUS VOLTAGE


Turn off all power supplying this equipment before working on it.
Failure to follow this instruction will result in death or serious injury.

TENSIÓN PELIGROSA

Desenergice el equipo antes de realizar cualquier trabajo en él.
El incumplimiento de esta precaución podrá causar la muerte o lesiones serias.

TENSION DANGEREUSE

Coupez toutes les alimentations de l'équipement avant toute intervention.
Le non-respect de ces instructions peut engendrer la mort ou des blessures graves.





	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²	 mm ²
	1...6	1...6	1,5...10	1,5...6	1...10	1...6	10 mm 3/8 in.	Ø 6,35 Phillips N° 2	1,7 15	Ø 4
	0,34... 1,5	0,75... 1,5	0,75... 1,5	0,75... 1,5	0,75... 1,5	0,75... 1,5	8 mm 5/16 in.	Ø 5 Phillips N° 1	0,8...1,2 10	Ø 3

AWG 18 = 0,82 mm² AWG 16 = 1,31 mm² AWG 14 = 2,08 mm² AWG 8 = 8,37 mm²





Schneider
Electric

30072-450-69A

LUALB1/LUALF1



LUALB1/LUALF1



LUALB1/LUALF1

