TEST REPORT

No. : GZIN1903011258MR
Date : Mar 29, 2019

GZIN1903011258MR

CUSTOMER NAME: NITTO DENKO (SHANGHAI SONGJIANG) CO., LTD

ADDRESS: 716 LIANYANG ROAD. SONGJIANG INDUSTRIAL ZONE SONGJIANG SHANGHAI CHINA

Sample Name : No.288EFR

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

SGS Ref. No.	:	SHIN1903015132MR; 14524009
Date of Receipt	:	Mar 18, 2019
Testing Start Date	:	Mar 18, 2019
Testing End Date	:	Mar 29, 2019
Test result(s)	:	For further details, please refer to the following page(s) (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. GZ Branch Testing Center

Doris Yin
Authorized signatory

检验检测专用章 Inspection & Testing Services
SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre-Materials & Reliability Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86–20) 82155555 f (86–20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编:510663 t (86–20) 82155555 f (86–20) 82075188 e sgs.china@sgs.com

TEST REPORT


No. : GZIN1903011258MR
Date : Mar 29, 2019

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Oxygen Index	ASTM D2863-17a	25.3%	Pass

Note: Pass : Meet the requirements;
Fail : Does not meet the requirements;
/ : Not Apply to the judgment.

Original Sample Photo:



Sample A

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre Materials & Reliability Laboratory.
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编:510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

TEST REPORT

No. : GZIN1903011258MR
Date : Mar 29, 2019

Test Item: Oxygen Index

Sample Description: Tape

Test Method: ASTM D2863-17a

Test Condition:

Specimen: Type Ⅴ

Specimen thickness: 0.12mm

Ignition procedure: Procedure B

Lab Environment Condition: (23±2)℃, (50±5)%RH

Test Result:

Test Item	Test Result	Clients' requirement	Conclusion
Oxygen Index	25.3%	＞23.5%	Pass

Note:

1. Burning behavior: erratic burning.
2. Test specimens were cut from the sample.

Test Photo:



During test



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre-Materials & Reliability Laboratory.
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编:510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZIN1903011258MR
Date : Mar 29, 2019

	
Before test	After test

Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Oxygen Index Tester	Oxygen Index	GZMR-PL-E108	2019-01-07	2019-07-06

******** End of report********

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services Co.,Ltd. Guangzhou Branch Testing Centre Materials & Reliability Laboratory
198 Kezhu Road, Scientech Park Guangzhou Economic & Technology Development District, Guangzhou, China 510663 t (86-20) 82155555 f (86-20) 82075188 www.sgsgroup.com.cn
中国・广州・经济技术开发区科学城科珠路198号 邮编:510663 t (86-20) 82155555 f (86-20) 82075188 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)